



PRIVATE SITE INSPECTION

Private Site Inspection Report

A fictional example showing the structure of a Trustline Builds deliverable.

ILLUSTRATIVE SAMPLE - NO CUSTOMER DATA

PREPARED FOR

Sample Client

PROPERTY

Illustrative Property

REPORT REFERENCE

Not applicable - illustrative sample

VERIFICATION

Disabled for this public sample

OVERALL ASSESSMENT

ATTENTION REQUIRED

SELECTED EVIDENCE

SITE EVIDENCE



REPRESENTATIVE FINDING

Two masonry joints require correction before the next lift.

RECOMMENDATION

RECOMMENDED NEXT ACTION

Ask for the affected joints to be corrected before work continues.